

#### State of Utah

### Department of **Natural Resources**

MICHAEL R. STYLER Executive Director

## Division of Oil, Gas & Mining

JOHN R. BAZA Division Director JON M. HUNTSMAN, JR. Governor

GARY R. HERBERT Lieutenant Governor

#### Representatives Present During the Inspection:

Rusty Netz Environmental Coordinator Karl Houskeeper Environmental Scientist III

# **Inspection Report**

Permit Number:	C0070042		
Inspection Type:	PARTIAL		
Inspection Date:	Thursday, February 21, 2008		
Start Date/Time:	2/21/2008 8:00:00 AM		
End Date/Time:	2/21/2008 11:00:00 AM		
Last Inspection:	Thursday, January 17, 2008		

Inspector: Karl Houskeeper, Environmental Scientist III

Weather: Clear, Temp. 32 Deg. F. InspectionID Report Number: 1557

Accepted by: dhaddock

3/5/2008

Permitee: SUNNYSIDE COGENERATION ASSOCIATES Operator: SUNNYSIDE COGENERATION ASSOCIATES

Site: STAR POINT REFUSE

Address: ONE POWER PLANT RD, PO BOX 159 SUNNYSIDE UT 84539

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Mineral Ownership

Types of Operations

152.81 Total Permitted 88.78 **Total Disturbed** Phase I Phase II Phase III

**Current Acreages** 

☐ Federal ☐ State

Surface ☐ Loadout

County Fee

Other

Processing ✓ Reprocessing

Underground

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Pending actions: No pending actions.

Inspector's Signature:

Date

Thursday, February 21, 2008

Karl Houskeeper, Environmental Scientist III

Inspector ID Number: 49

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

1594 West North Temple, Suite 1210, PO Box 145801, Salt Lake City, UT 84114-5801 telephone (801) 538-5340 • facsimile (801) 359-3940 • TTY (801) 538-7458 • www.ogm.utah.gov Permit Number: C0070042 Inspection Type: PARTIAL

Inspection Date: Thursday, February 21, 2008

Page 2 of 3

#### REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
  - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
  - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcemen
1.	Permits, Change, Transfer, Renewal, Sale	$\checkmark$		$\checkmark$	
2.	Signs and Markers	✓		<b>V</b>	
3.	Topsoil				
4.a	Hydrologic Balance: Diversions	<b>✓</b>		✓	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments				
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring	<b>V</b>	✓		
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives	<b>V</b>	✓		
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments	<b>✓</b>		<b>V</b>	
8.	Noncoal Waste				
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.a	Roads: Construction, Maintenance, Surfacing	✓		✓	
16.b	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Permit Number: C0070042 Inspection Type: PARTIAL

Inspection Date: Thursday, February 21, 2008

Page 3 of 3

#### 1. Permits, Change, Transfer, Renewal, Sale

Pending actions: No pending actions.

#### 2. Signs and Markers

The mine ID signs are located at the contact points of the public road to the permit area and contains all of the appropriate information. All other signs and markers observed during the inspection were in compliance with the approved MRP.

#### 4.a Hydrologic Balance: Diversions

Snow has been removed from diversions that was noted on the previous inspection.

## 7. Coal Mine Waste, Refuse Piles, Impoundments

The Refuse pile appeared stable, no visible hazards or smokers. The surface of the refuse pile is being excavated in lifts by a track hoe and then loaded into trucks by a loader.

## 16.a Roads: Construction, Maintenance, Surfacing

Warmer temperatures have cause the snow pack to melt causing graveled roadways to be mushy and muddy. As temperatures continue to warm and the frost level decreases several road ways will need maintenance.